



Release Note

Software Version: 2.4.12

Models: H2U

Date: 2021.08.16



Content

- Content..... 2**
- 1 Revise History.....3**
- 2 Release 2.4.12.....4**
 - 2.1 New Features.....4
- 3 Release 2.4.9.....5**
 - 3.1 New Features.....5
 - 3.2 Optimization.....5
 - 3.3 Bug Fix.....6

1 Revise History

No.	Version	Release Time
1	2.4.9	2021.07.02
2	2.4.12	2021.08.16

2 Release 2.4.12

Models	Software Version	Comment
H2U	2.4.12	

2.1 New Features

1. Add the function of prohibiting the downgrade of software

3 Release 2.4.9

Models	Software Version	Comment
H2U	2.4.9	

3.1 New Features

1. Add the function that restore factory setting by entering the key combination in standby
2. Add the diagnostic function of traceroute on the web page
3. Add RTCP-XR function
4. Add RTP Relay function
5. Add Call Timeout function
6. Support users to customize the color of the power light
7. Add the function that support to report IP by the long pressing "#" in standby mode

3.2 Optimization

1. Improve the function of Action plan
2. The extended number of Display Name is max to 64 characters
3. Improve dialplan rules and rules of support'!', 'T' and','
4. Fix the problem that the memory will not be released when there are too many TR069 messages, causing the phone to be abnormal
5. RTP Keep Alive is enabled by default

6. Modify the enable change port configuration item. The default value is 1

3.3 Bug Fix

1. Fix the problem that the dial plan cannot be deleted from the webpage
2. Fix the problem of phone abnormality caused by RTCP-XR
3. Fixed the abnormal problem that occurred when the phone was placed for a period of time during IP conflict