



Release Note

Software Version: 2.4.13.x

Models: X3V/H3W/H5W

Date: 2023.11.17



Content

Content	2
1 Revise History	3
2 Release 2.4.13.x	4
2.1 Optimization	4
3 Release 2.4.12.5	5
3.1 New Features	5
3.2 Optimization	5
3.3 Bug Fix	5
4 Release 2.4.10.2	7
4.1 New Features	7
4.2 Optimization	7
4.3 Bug Fix	7
5 Release 2.4.5.1	8
5.1 New Features	8
5.2 Bug Fix	8
5.3 configuration parameter	8

1 Revise History

No.	Version	Release Time
1	2.4.5.1	2021.8.2
2	2.4.10.2	2022.2.11
3	2.4.12.5	2023.2.13
4	2.4.13.x	2023.11.17

2 Release 2.4.13.x

Models	Software Version	Comment
X3V/H3W/H5W	2.4.13.x	

2.1 Optimization

1. Enhanced the TR069 functionality.
2. Improved the call waiting feature.

3 Release 2.4.12.5

Models	Software Version	Comment
X3V/H3W/H5W	2.4.12.5	

3.1 New Features

1. Addition of Croatian
2. Add Japanese
3. Port SIP PBX Call Park Compatibility

3.2 Optimization

1. Optimizing DNS Query Mode
2. Optimization of French-language translation documents
3. Optimization of automated deployment-related issues
4. Optimize the time to return the Dsskey Home interface from other Dsskey interfaces
5. Optimize the phone to receive calls with Reason field from Cancele as received calls in the call log
6. Extended LDAP Server Address Word Limit

3.3 Bug Fix

1. Fix Phone Page Upgrade Dsskey Icon Help Message Error
2. Fix the problem that the LED light on the sub-screen of the phone does not change with the page number of the sub-screen

3. Fixing problems related to abnormalities in the use of Internet telephone books
4. Fix Unstable Phone Calls under WiFi
5. Fix the problem of sending STUN packets when STUN is turned off under special server
6. Fix the problem of delay in answering the call using the handle to set up the call

4 Release 2.4.10.2

Models	Software Version	Comment
X3V/H3W/H5W	2.4.10.2	

4.1 New Features

1. The phone supports setting startup logo image after it is upgraded on web page
2. Add anti-degradation function to the phone
3. The phone supports to display the information of Uboot version

4.2 Optimization

4. Optimize translation issues related to contacts
5. Optimize the WiFi driver issue of hotel phone, and support the automatic adjustment of frequency offset function
6. Optimize the issue that the phone turns off the TR069 prompt tone by default

4.3 Bug Fix

1. Fix the problem that the Wi-Fi MAC address displayed on the LCD of the phone does not match the actual Wi-Fi MAC address obtained by the phone
2. Fix the problem of IP conflict when the phone uses WiFi and wired network at the same time

5 Release 2.4.5.1

Models	Software Version	Comment
X3V	2.4.5.1	

5.1 New Features

1. Add local six party conference function
2. Add Wi-Fi IP, Wi-Fi SSID and Wi-Fi MAC fields to the network page

5.2 Bug Fix

1. Fixed the problem that the phone cannot forward packets without tag after opening the LAN port VLAN
2. Fixed the problem that the phone automatically switches to the AP with weak signal in some cases
3. Fixed the problem that the incoming ring of the phone can only ring through the headset after group ring is turned on
4. Fixed the problem that the phone cannot connect automatically when importing the Wi-Fi connected configuration file
5. Fixed the problem that Wi-Fi could not be searched occasionally in some cases

5.3 configuration parameter

1. Add energy saving mode

Fanvil Technology Co., Ltd

Add: 10F, Block A, Dualshine Global Science Innovation Center, Honglang North 2nd Road, Bao'An District, Shenzhen, China
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com 8 / 9

Function	Configuration File	Permitted Value	Default Value	Action	Description
Energy saving mode	Intelligent Power Saving: 0 (默认为 1)	0 or 1	1	On or off	Phone web page -> phone settings-> function settings-> energy saving mode-> turn on or off power saving (on by default)