Release Note

Software Version：2.0.1

Models：X1SP/X3U/X3SG/X1SG

Date：2020.5.12

Content

1   Revise History

No.	Version	Release Time
1	2.0.1	2020.5.12

2 Release 2.0.1

Models	Software Version	Comment
X1SP/X3U/X3SG/X1SG	2.0.1	

2.1 New Features

1. Add Portuguese to Web page

2. Support customizable BLF setting

2.2 Optimization

1. Automatic certificate upgrade. Support package upgrade.

2. Optimize the display of UI front

3. Add the display of the last run time on Web

4. Add the IP conflict reminder on LCD

5. Add the configuration of Enable DTMF/Transfer/Hold/Conference on Web

6. Add the reminder of password modification when the registration password is default.

2.3 Bug Fix

1. Fix the issue of invalid webFliter after configuration

2. Fix the issue of IP phone crash when using the G.726 codec in communication under the special situation.

3. Fix the issue that the headphone is soundless when the call is answered automatically in group ring mode.

4. Fix the issue of the memory leak after multiple communications through uaCSTA.

5. Fix the abnormal issue of ptime setting.

6. Fix the issue that IP phone cannot receive IP address because of the wrong Vlan ID received through option132.

7. Fix the issue of abnormal issue of Networks after the phone has sent more that 2W data package in 30 seconds.

8. Fix the issue of no prompt when clicking the upload button with empty equipment certificate.

9. Fix the issue that dial query page does not support fuzzy query.

10. Fix the issue that dial pad cannot be light up after pressing the button of the base of EHS headphone.

11. Fix the issue that the call log cannot be deleted after resetting.