Fanvil

Release Note

Software Version：2.12.0

Models：H2U-V2

Date：2022.11.22

Content

1   Revise History

No.	Version	Release Time
1	2.4.8.1	2022.5.5
2	2.4.8.2.1	2022.8.19
3	2.12.0	2022.11.22

Fanvil Technology Co., Ltd

2   Release 2.12.0

Models	Software Version	Comment
H2U-V2	2.12.0	

2.1   Bug fix

1. Fixes Vlan functionality in special cases

2. Fix a web page configuration quick dial save exception

3. Fix issues where Alert-Info ringtones do not work out

4. Fix the distortion of the incoming sounds played through the hands-free speaker

3   Release 2.4.8.2.1

Models	Software Version	Comment
H2U-V2	2.4.8.2.1	

3.1   Optimization

1.Optimize translation issues related to contacts

Fanvil Technology Co., Ltd

4　Release 2.4.8.1

Models	Software Version	Comment
H2U-V2	2.4.8.1	

4.1　Differences between H2U and H2U-V2

	H2U　Phone	H2U-V2 Phone
Model	H2U	H2U-V2
Vendor Identifier	Fanvil H2U	Fanvil H2U -V2
HTTP User Agent/ SIP User Agent	H2U	H2U-V2
Start-up speed	90S	20S
Codecs	G.711U,G.711A,G726,G.729AB ,iLBC,Opus,G.722	G.711U,G.711A,G726,G.729AB ,Opus,G.722,G.723.1

4.2　Optimization

1.　Optimize the default hands-free volume value of 7

2.　Modify the default configuration Check FailTimes to1

4.3　Bug Fix

1.　Fix the problem of automatic deployment failure for special servers

Fanvil Technology Co., Ltd

Add:10F, Block A, Dualshine Global Science Innovation Center, Honglang North 2nd Road, Bao'An District, Shenzhen, China
Tel: +86-755-2640-2199　Fax: +86-755-2640-2618　Email: support@fanvil.com　www.fanvil.com

6 / 6