



Release Note

Software Version: 2.6.0.350

Models: X7A

Date: 2021.7.10



Content

Content.....	2
1 Revise History.....	3
2 Release 2.6.0.350.....	4
2.1 New Features.....	4
2.2 Optimization.....	4
2.3 Bug Fix.....	4
3 Release 2.6.0.125.....	6
3.1 Optimization.....	6
3.2 Bug Fix.....	6
4 Release 2.4.0.6.....	7
4.1 New Features.....	7
5 Release 2.2.0.229.....	8
5.1 New Features.....	8
5.2 Optimization.....	8
5.3 Bug Fix.....	8

1 Revise History

No.	Version	Release Time
1	2.2.0.229	2020.12.31
2	2.4.0.6	2021.1.16
3	2.6.0.125	2021.3.23
4	2.6.0.350	2021.7.10

2 Release 2.6.0.350

Models	Software Version	Comment
X7A	2.6.0.350	

2.1 New Features

1. LCD add Korean translation
2. Add dynamic multicast function

2.2 Optimization

1. Compatible with Jabra EHS headset
2. Optimize the font size of the video page

2.3 Bug Fix

1. Fixed the problem that the LCD display is abnormal when answering a video call
2. Fixed the related problems of intercom broadcast app
3. Fixed the abnormal status of feature sync dnd

Fanvil Technology Co., Ltd

Add: 10F, Block A, Dualshine Global Science Innovation Center, Honglang North 2nd Road, BaoAn District, Shenzhen, China
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com

4. Fixed the problem that the daylight saving time setting is modified but does not take effect after restart
5. Fixed the problem that the settings cannot be modified when the gateway and static IP are not in the same network segment
6. Fixed the problem of abnormal network information acquisition under special circumstances
7. Fixed a problem that the sync clock time feature did not take effect
8. Fixed the problem that the telephone can not transfer calls under special circumstances
9. Fixed the abnormal setting interface such as closing blacklist in the drop-down main interface
10. Fixed the problem that the number in the from field is not displayed during IP calls

3 Release 2.6.0.125

Models	Software Version	Comment
X7A	2.6.0.125	

3.1 Optimization

1. Optimized the issue that the ldap contacts can directly enter the search interface after downloading
2. The screen saver is enabled by default. Extend the timeout range of the screen saver.
3. Optimize the webpage translation files

3.2 Bug Fix

1. Fix the problem of abnormal earphone loudness during a call

4 Release 2.4.0.6

Models	Software Version	Comment
X7A	2.4.0.6	

4.1 New Features

1. Add Bluetooth external line Function
2. Add EHS headset Function

5 Release 2.2.0.229

Models	Software Version	Comment
X7A	2.2.0.229	

5.1 New Features

1. Added the language of Russian, French, and Spanish
2. Added the support for setting network priority
3. Added the support for DHCP Option120

5.2 Optimization

1. Optimize the recognition and compatibility of large-capacity TF card
2. Optimize the related issues of unsMOOTH video call

5.3 Bug Fix

1. Fixed the playback issues of Bluetooth speaker
2. Fixed the problem that the LED lights of the corresponding function keys do not change when the phone calls park
3. Fixed an issue that the IP address saved in the contact could not be called out without registering a SIP account
4. Fixed the problem of incorrect display of daylight saving time in individual countries
5. Fixed the problem that the opposite end video cannot not be displayed after transformation
6. Fixed the problem that the device cannot display the video from the other side when calling without a camera.

Fanvil Technology Co., Ltd

Add: 10F, Block A, Dualshine Global Science Innovation Center, Honglang North 2nd Road, BaoAn District, Shenzhen, China
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com

7. Fixed the problem that when the phone makes an outgoing call, the server will reply with 18X with SDP, and the phone will play the local ring and the ring of server at the same time