



## **Release Note**

**Software Version:** 2.6.10.988

**Models:** X7A

**Date:** 2024.3.15



## Content

---

<b>Content.....</b>	<b>2</b>
<b>1 Revise History.....</b>	<b>3</b>
<b>2 Release Version 2.6.10.988 .....</b>	<b>4</b>
2.1 New Features .....	4
2.2 Optimization.....	4
2.3 Bug Fix .....	4
<b>3 Release 2.6.0.1282 .....</b>	<b>6</b>
3.1 New Features .....	6
3.2 Optimization.....	6
<b>4 Release 2.6.0.1153 .....</b>	<b>7</b>
4.1 New Features .....	7
4.2 Optimization.....	7
4.3 Bug Fix .....	8
<b>5 Release 2.6.0.350 .....</b>	<b>10</b>
5.1 New Features .....	10
5.2 Optimization.....	10
5.3 Bug Fix .....	10
<b>6 Release 2.6.0.125 .....</b>	<b>12</b>
6.1 Optimization.....	12
6.2 Bug Fix .....	12
<b>7 Release 2.4.0.6 .....</b>	<b>13</b>
7.1 New Features .....	13
<b>8 Release 2.2.0.229 .....</b>	<b>14</b>
8.1 New Features .....	14
8.2 Optimization.....	14
8.3 Bug Fix .....	14

## 1 Revise History

---

No.	Version	Release Time
1	2.2.0.229	2020.12.31
2	2.4.0.6	2021.1.16
3	2.6.0.125	2021.3.23
4	2.6.0.350	2021.7.10
5	2.6.0.1153	2022.8.24
6	2.6.0.1282	2023.1.6
7	2.6.10.988	2024.3.15

## 2 Release Version 2.6.10.988

---

Models	Software Version	Comment
X7A	2.6.10.988	

### 2.1 New Features

1. Iteratively update the brand new UI interface
2. Dsskey can support 116 shortcut keys
3. Supports IPv6 and IPv4&IPv6 modes
4. Add the function of adding voice conference members through multiple selections
5. Add push XML function
6. Add DND large icon function

### 2.2 Optimization

1. Optimize the proxy interface to support the selection of proxy login status function
2. Optimize Block XML When Call configuration and adapt to push numeric buttons
3. Optimize key processing in the xmlbrowser section
4. Optimize the import function of Dsskey settings
5. Optimize compatibility issues with Ampitech access control cameras
6. Optimize software security issues

### 2.3 Bug Fix

1. Modify the issue of the phone not being able to answer calls when using the

Fanvil Technology Co., Ltd

Add: 10F, Block A, Dualshine Global Science Innovation Center, Honglang North 2nd Road, BaoAn District, Shenzhen, China  
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com

built-in app

2. Modify the issue of the phone not being able to refresh the session timer when establishing a call
3. Modify the hierarchy issue of Ldap phone book display type to List
4. Modify the color change issue of the softkey icon in the sliding pre dial interface
5. Modify the issue of not displaying XML phone book contacts on the webpage
6. Modify the issue of missing content in the Action URL issued by FDMCS

### 3 Release 2.6.0.1282

---

Models	Software Version	Comment
X7A	2.6.0.1282	

#### 3.1 New Features

1. Support 3-party video conference
2. Support 10-party audio and video hybrid conference (up to 2-party video calls included)

#### 3.2 Optimization

1. Optimize USB compatibility related issues

## 4 Release 2.6.0.1153

---

Models	Software Version	Comment
X7A	2.6.0.1153	

### 4.1 New Features

1. The function of pressing the return key to hang up when there is an incoming call / a call is added to the web page.
2. The Call-id in the SIP protocol supports the user-custom field functionality.
3. A new display type configuration item is added on the web page, which supports search and list.
4. Whether a popup configuration is added on the page.
5. Extended function key URL subtype.
6. Compatible with the Huawei enterprise address book.

### 4.2 Optimization

1. Optimize the XML Browser functionality.
2. Optimize contact-related translation issues.

3. Optimize the call ringing tone for a small sound problem.
4. Optimize device popup button color is blue.
5. Optimize the device in screensaver / hibernation, press the number key to open the dial and enter the number key into the dial.
6. Optimize the Huawei phone book incoming call interface.
7. Optimize video call compatibility-related issues.

### **4.3 Bug Fix**

1. Fix the problem of repeated display of call records.
2. Fix When OK key is None, long pressing OK key will not restore the factory.
3. Fix the problem of automatic recording jam after transfer.
4. Fix the problem that the search result cannot be found when inputting full characters when querying contacts.
5. Fix the problem that the RTP is selected as optional, and the peer can't hear hold music by pressing hold.

6. Fix the problem after calls different two numbers, the call record shows only one of the numbers.
7. Fix issues that automatic deployment cannot send DHCP Option 66 and 120 in special cases.
8. Fixed that the LDAP query name cannot be updated to the call record.
9. Fix black screen problems with answering video calls in special situations.
10. Fixed the Select H.265 encoded video call not displaying the image.
11. Fix the abnormal Android phone and postsip softphone video call tests.
12. Fix the select G.722 coding call exception after receiving a special length of voice data.
13. Fix the ldap domain name resolution problem.
14. Fix the problem of configuring recording in action plan and not stopping recording when hold.

## 5 Release 2.6.0.350

---

Models	Software Version	Comment
X7A	2.6.0.350	

### 5.1 New Features

7. LCD add Korean translation
8. Add dynamic multicast function

### 5.2 Optimization

1. Compatible with Jabra EHS headset
2. Optimize the font size of the video page

### 5.3 Bug Fix

1. Fixed the problem that the LCD display is abnormal when answering a video call
2. Fixed the related problems of intercom broadcast app
3. Fixed the abnormal status of feature sync dnd

Fanvil Technology Co., Ltd

Add: 10F, Block A, Dualshine Global Science Innovation Center, Honglang North 2nd Road, BaoAn District, Shenzhen, China  
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com

4. Fixed the problem that the daylight saving time setting is modified but does not take effect after restart
5. Fixed the problem that the settings cannot be modified when the gateway and static IP are not in the same network segment
6. Fixed the problem of abnormal network information acquisition under special circumstances
7. Fixed a problem that the sync clock time feature did not take effect
8. Fixed the problem that the telephone can not transfer calls under special circumstances
9. Fixed the abnormal setting interface such as closing blacklist in the drop-down main interface
10. Fixed the problem that the number in the from field is not displayed during IP calls

## 6 Release 2.6.0.125

---

Models	Software Version	Comment
X7A	2.6.0.125	

### 6.1 Optimization

1. Optimized the issue that the ldap contacts can directly enter the search interface after downloading
2. The screen saver is enabled by default. Extend the timeout range of the screen saver.
3. Optimize the webpage translation files

### 6.2 Bug Fix

1. Fix the problem of abnormal earphone loudness during a call

## 7 Release 2.4.0.6

---

Models	Software Version	Comment
X7A	2.4.0.6	

### 7.1 New Features

1. Add Bluetooth external line Function
2. Add EHS headset Function

## 8 Release 2.2.0.229

---

Models	Software Version	Comment
X7A	2.2.0.229	

### 8.1 New Features

1. Added the language of Russian, French, and Spanish
2. Added the support for setting network priority
3. Added the support for DHCP Option120

### 8.2 Optimization

1. Optimize the recognition and compatibility of large-capacity TF card
2. Optimize the related issues of unsMOOTH video call

### 8.3 Bug Fix

1. Fixed the playback issues of Bluetooth speaker
2. Fixed the problem that the LED lights of the corresponding function keys do not change when the phone calls park
3. Fixed an issue that the IP address saved in the contact could not be called out without registering a SIP account
4. Fixed the problem of incorrect display of daylight saving time in individual countries
5. Fixed the problem that the opposite end video cannot not be displayed after transformation
6. Fixed the problem that the device cannot display the video from the other side when calling without a camera.

Fanvil Technology Co., Ltd

Add: 10F, Block A, Dualshine Global Science Innovation Center, Honglang North 2nd Road, BaoAn District, Shenzhen, China  
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com

7. Fixed the problem that when the phone makes an outgoing call, the server will reply with 18X with SDP, and the phone will play the local ring and the ring of server at the same time