



# **Release Note**

Software Version: 2.14.0.23

Models: W611W

Date: 2024.4.30



# Content

Conten	t	2
1 Revis	se History	4
2 Relea	ise 2.14.0.23	5
2	.1 New Features	5
2	.2 Optimizations	5
2	2.3 Bug Fix	5
2	2.4 New Feature Description	6
3 Relea	ase 2.14.0.19	9
3	3.1 New Features	9
3	2.2 Optimizations	9
4 Relea	ase 2.14.0.4	0
4	.1 Bug Fix1	0
5 Relea	se 2.14.0.3	1
5	i.1 New Features1	1
5	5.2 Optimizations1	1
5	i.3 Bug Fix1	1
5	.4 Known Issues	2
6 Relea	ase 2.12.5.7	3
6	5.1 Optimizations	3
6	i.2 Bug Fix1	3
7 Relea	se 2.12.5.4	4
7	'.1 New Features1	4
7	.2 Optimizations	4
7	7.3 Bug Fix1	4
7	7.4 New feature description	5
8 Relea	rse 2.12.4.16	7
8	3.1 New Features	7
8	3.2 Optimizations1	7
8	3.3 Bug Fix1	7
8	3.4 New feature description	7
9 Relea	ase 2.12.4.14	0
9	0.1 New Features	0



9.2 Optimization	20
9.3 Bug Fix	20
9.4 New feature description	20



# 1 Revise History

No.	Version	Release Time
1	2.12.4.14	2022.11.21
2	2.12.4.16	2023.3.2
3	2.12.5.4	2023.6.12
4	2.12.5.7	2023.7.17
5	2.14.0.3	2023.9.21
6	2.14.0.4	2023.9.25
7	2.14.0.19	2024.1.25
8	2.14.0.23	2024.4.30



Models	Software Version	Comment
W611W	2.14.0.23	

#### 2.1 New Features

- 1. Add the function of sharing WiFi;
- 2. Add A.I Noise Reduction Technology and Acoustic Enclosure;
- 3. Add Arabic language displaying;
- 4. Add a configuration item for low battery tone.

## 2.2 Optimizations

- 1. The device can be woken up by Push XML message when sleeping;
- 2. Block the function of pressing and holding the OK button when idle to factory reset, in order to avoid misoperation;
- 3. The left and right navigation keys of the dialing status can be used to switch between lines;
- 4. Optimize the stability of hotspot connection during hibernation.

## 2.3 Bug Fix

- 1. Fix the problem of missing configuration in specific cases;
- 2. Fix the problem that the phone frequently sends registration messages;
- 3. Fix the problem that the phone could not receive incoming calls occasionally during hibernation;
- 4. Fix the problem of garbled characters when LCD displays Japanese;
- 5. Fix the one-way audio issue during the call under a specific server.



## 2.4 New Feature Description

#### 1. Add the function of sharing WiFi;

Description: 1) The device has a built-in WiFi with a fixed SSID and password, and when there is an AP with the same configuration in the environment, the phone can automatically connect to this AP after powering on to obtain a WiFi IP.



2) After the user connects to an AP, the user can enter [Menu] > [Advanced Settings] > [Share WiFi] on the device, turn on the WiFi sharing function, fill in the SSID, security mode, and password of the AP, and other devices that do not have any known network except the fixed SSID can automatically obtain this WiFi to realize the WiFi sharing function.






### 2. Add A.I Noise Reduction Technology and Acoustic Enclosure;

Description: Users can enable the **A.I Noise Reduction Technology** or **Acoustic Enclosure** from the device's web page> [Phone Settings]> [Media Settings] > [Noise Reduction].



## 3. Add Arabic language displaying;

Description: Users can import the configuration "Default Language:ar" through the web page, or select Arabic through the LCD > [Menu]> [Settings] > [Language] to change the language displayed on the device screen to Arabic.



#### 4. Add a configuration item for low battery tone.

Description: User can set whether to turn on the low battery tone through the [Phone Settings] > [Features] > [Tone Settings] on the web page, or turn on the low battery tone by importing the configuration "Low Battery Tone:1".

When the low battery tone is turned off, only the indicator light and pop-up



prompt will be shown when the battery is low. When the low battery tone is turned on and the battery is low, the indicator light and pop-up prompt will be displayed and the phone will play the low battery tone.





Models	Software Version	Comment
W611W	2.14.0.19	

#### 3.1 New Features

1. When the LCD language is English, add an input method of "aB2" type.

# 3.2 Optimizations

- 1. Optimize the display of web page information;
- 2. Optimize the display of LCD screen information;
- 3. Optimize the stability of Wi-Fi connection;
- 4. Optimize the system power consumption and extend the standby time of the device;
- 5. The extended LDAP username character length is 127 bits;
- 6. Optimize LCD screen battery power icon color, white when not charging;
- 7. Adjust and optimize the five-compartment distribution of the device's battery power;
- 8. SIP authentication support SHA-256 encryption algorithm to solve the problem that there will not be response after receiving SIP 401 authentication under special circumstances



Models	Software Version	Comment
W611W	2.14.0.4	

# 4.1 Bug Fix

1. Fixed an issue where the WiFi coupling test failed.



Models	Software Version	Comment
W611W	2.14.0.3	

### 5.1 New Features

2. When the LCD language is English, add an input method of "aB2" type.

## 5.2 Optimizations

- 9. Optimize the display of web page information;
- 10. Optimize the display of LCD screen information;
- 11. Optimize the stability of Wi-Fi connection;
- 12. Optimize the system power consumption and extend the standby time of the device;
- 13. The extended LDAP username character length is 127 bits;
- 14. Optimize LCD screen battery power icon color, white when not charging;
- 15. Adjust and optimize the five-compartment distribution of the device's battery power;
- 16. SIP authentication support SHA-256 encryption algorithm to solve the problem that there will not be response after receiving SIP 401 authentication under special circumstances

# 5.3 Bug Fix

1. Fixed the issue that after the W611W enables general name verification, the verification of certificates using the SIP TLS protocol fails;

**Fanvil** 

2. Fixed the issue that when the W611W is charging, an abnormality prompt

occasionally appears;

3. Fixed the issue where the W611W ROM is displayed as 0 under special

circumstances;

4. Fixed the issue that after connecting to FDMCS, the online status is

displayed in FDMCS is inaccurate;

5. Fixed an issue where when charging through the charging base, W611W

occasionally appeared as always charging and did not prompt full charge

status.

5.4 Known Issues

1. Description: LCD probabilistic screen shifts;

**Temporary scheme:** The device re-enters hibernation and resumes after

waking up again.

2. **Description:** The device crashes probabilistically during hibernation;

**Temporary scheme:** The device automatically restarts and resumes after an

abnormality.

3. **Description:** Occasionally, the Wi-Fi connection fails or the Wi-Fi cannot

be scanned;

**Temporary scheme:** After the Wi-Fi abnormality occurs, the device

automatically detects the abnormality and recovers it every 10 minutes.

4. **Description:** After the device is used for a period of time and calls exceed

3,000 times, the memory occupation causes stuttering, ringing, and

answering delays of 1-2 seconds;

Temporary scheme: When the device detects that it is out of memory, it

automatically restarts and recovers.

Fanvil Technology Co., Ltd



## 6 Release 2.12.5.7

Models	Software Version	Comment
W611W	2.12.5.7	

## 6.1 Optimizations

17. Optimize system power consumption, synchronously turn off the keyboard backlight after the screen is extinguished during a call

## 6.2 Bug Fix

- 1. Fix the problem that W611W keeps dropping after successful registration under certain circumstances;
- 2. Fix the issue where a new page of dsskeys could not be added on the web page;
- 3. Fix the issue where the phone was abnormal when a memory key was configured;
- 4. Fix the issue where SSID was displayed incompletely in some pages



#### 7 Release 2.12.5.4

Models	Software Version	Comment
W611W	2.12.5.4	

#### 7.1 New Features

- 1. Add Japanese;
- 2. Add the function of password display when entering Wi-Fi password;
- 3. Add the function of customizing WiFi roaming threshold;
- 4. Add the function of displaying the MAC and signal strength of the connected AP.

## 7.2 Optimizations

- 18. Optimize system power consumption and extend the standby time of the device;
- 19. Optimize Russian translation;
- 20. Optimize French translation;
- 21. Optimize the stability of WiFi connection;
- 22. Extend the LDAP phonebook SearchBase and username length to 127 bytes.

# 7.3 Bug Fix

- 1. Fix the issue that W611W is often offline after being deployed in FDMCS;
- 2. Fix the issue that pushing a new version for W611W through FDMCS failed.



## 7.4 New feature description

#### 1. Add Japanese.

Function description: Add Japanese option to the language list on the web and LCD side.

2. Add the function of password display when entering Wi-Fi password.

Function description: When entering a Wi-Fi password or modifying saved network information on the web side, you can see the entered Wi-Fi password in clear text by selecting [Password Display] or clicking the logo \*\*.





3. Add the function of customizing WiFi roaming threshold;

Function description: On the website [Network] > [Wi-Fi Settings], users can set [Roaming Gain]. When the device's signal strength is less than -67dB and other available APs are detected to be higher than the current AP signal strength by the setting value, roaming switching will be performed.





4. Add the function of displaying the MAC and signal strength of the connected AP.

Function description: Users can view the BSSID of the currently connected AP and the current signal strength in the [Menu]> [Status] > [Network] on the LCD.





### 8 Release 2.12.4.16

Models	Software Version	Comment
W611W	2.12.4.16	

#### 8.1 New Features

- 5. Add the function to customize encryption of the menu APP;
- 6. Add the ability to lock and unlock the keyboard by long pressing "#";
- 7. OpenVPN supports TLS authentication.

## 8.2 Optimizations

- 23. Optimize WiFi synchronization configuration function;
- 24. Optimize W611W handset loudness.

## 8.3 Bug Fix

- 3. Fix the issue that incoming calls could not be received occasionally during hibernation;
- 4. Optimize Wi-Fi connection, such as the problem that the AP device cannot reconnect after the terminal is disconnected in some cases

# 8.4 New feature description

1. Add the function to customize encryption of the menu APP

Feature description: Users can select the application in the menu to be encrypted, and the encrypted application needs to enter the menu password before accessing.

nc configurations are as follows:



screen. EncryptTheApp =		
Valid Values	• Status	
	● WLAN	
	• Basic	
	• Contact	
	• Message	
	• Calllog	
	• Features	
	<ul><li>Application</li></ul>	
	Use ","" between apps.	
	e.g.: Status, WLAN。	
Default Value	void	

Note: Advanced settings encryption is not affected by configuration.

2. Add the ability to lock and unlock the keyboard by long pressing "#"

Feature description: Web>Phone Settings>Advanced>Keyboard Lock Settings, when the keyboard lock type is disabled, users can long press the "#" to lock and unlock. This won't work when the keyboard lock type isn't disabled: users can long press "#" to enter password and jump to the keyboard lock settings; After it's locked, users can long press "#" to enter password and unlock the phone.

Web configurations are as follows:




3. OpenVPN supports TLS authentication.

Fanvil Technology Co., Ltd



Feature description: Web>Network>VPN, when OpenVPN server chooses TLS authentication, the phone will turn on OpenVPN, import TLS certifications and get VPN IP successfully.





### 9 Release 2.12.4.14

Models	Software Version	Comment
W611W	2.12.4.14	

#### 9.1 New Features

1. Add DSSKEY Page functionality to support setting up a two-page Dsskey

## 9.2 Optimization

- 1. Optimize the prompt language display during the shutdown
- 2. Optimize the Italian language translation
- 3. Optimize the AP density threshold as -67 dBM
- 8. Optimize the access level of WiFi settings directory

## 9.3 Bug Fix


- 1. Fix the problem of password displayed in plain text in the XML / NC configuration file
- 2. Fix the phone restart after the softkey is configured, and the problem of configuration cannot be saved
- 3. Fix after a device goes dormant, which not responding to a SIP Option message, causing the problem of a wire drop display on a particular server

## 9.4 New feature description

1.Add DSSKEY Page functionality to support setting up a two-page Dsskey Web Function Key> Function Key page, expanded from the existing Dsskey to two Dsskey, 8 dsskey per page. The Dsskey defaults are all None.

Fanvil Technology Co., Ltd





Configure the DSS Key on page N, set a softkey or navigation key to Dsskey PageN, press the softkey / navigation key of the corresponding interface, enter the Dsskey Page, select a DSS Key, or press the corresponding serial number of the DSS Key to perform the corresponding function.

