



Release Note

Software Version: 2.0.5

Models: X5S/X6/X210/X210i/X7/X7C/X4U/X5U/X6U

Date: 2020.5.12



Content

Content	2
1 Revise History	3
2 Release 2.0.5	4
2.1 Optimization.....	4
2.2 Bug Fix.....	4
3 Release 2.0.2	5
3.1 New Features.....	5
3.2 Optimization.....	6
3.3 Bug Fix.....	7

1 Revise History

No.	Version	Release Time
1	2.0.2	2020.3.31
2	2.0.5	2020.5.12

2 Release 2.0.5

Models	Software Version	Comment
X5S/X6/X210/X210i/X7/X7C /X4U/X5U/X6U	2.0.5	

2.1 Optimization

Compatible with uaCSTA function of Yeastar server

2.2 Bug Fix

There is a problem with the call record after resetting the device

3 Release 2.0.2

Models	Software Version	Comment
X5S/X6/X210/X210i/X7/X7C /X4U/X5U/X6U	2.0.2	

3.1 New Features

1. Add the function to customize UI colors
2. Add the function to preview peer-to-peer SIP video
3. Add the function to dynamic multicast
4. Add the language of Portuguese
5. Add the function to cancel Hold automatically once the current line changes
6. Add the function to achieve one-click Call Park / Retrieve by setting BLF list key
7. LCD side screen supports displaying the pushed XML message
8. Support sending Active URI by SIP Notify
9. Add the log output interface of WLAN on web page

3.2 Optimization

1. Improve the handling when IP Phones receive multi-channel Intercom
2. Support fuzzy matching for Contact search
3. Display the source for web pages time
4. Newly add the parameters, such as backup server, LAN VLAN and etc, to TR069
5. Add the related functions of HTTP API
6. X210i hotspot extension management supports displaying extension information and modifying grouping functions
7. Support sending VLAN ID in character string format under DHCP protocol
8. Improve the function that calling out with “a prefix+BLF”
9. Improve the default value of TLS version as 1.2

3.3 Bug Fix

1. Fix the issue of the phone memory leak caused by the situation that uaCSTA creates sessions for many times
2. Fix the issue of redirection deployment failure after the phone is reset
3. Fix the issue that there is no “Abc” in the input method when entering name or other text in contact column
4. Fix the compatibility issue of IE browser
5. Fix the issue of abnormal display when importing phone book in csv format
6. Fix the issue that the phone restarts abnormally when you establish a second call during a call by the 3CX server webclient
7. Fix the issue that the called party fails to hold after two extensions establish a call when they work as hotspots
8. Fix the issue that the pickup code is displayed in the call log after the call was picked up by calling the pickup code
9. Fix the issue that the configuration is still there even having cleared the configuration and then restart the phone in some cases
10. Fix the issue that the image is stuck in the phone answer interface when previewing video
11. Fix the issue that the multicast does not work when initiated by DSS key
12. Fix the issue that there is wrong info message when using uaCsta to call a nonexistent number
13. Fix the issue of the abnormal display for call logs when there is a special field of phone-context
14. Fix the issue that when ptime is 10, the phone will try to send 4 registration messages when registering