



## **Release Note**

Software Version: 2.10.1

Models: X1/X2/X2C/X3S/X4/H2S/H3/H5

Date: 2019-09-04



## **Optimization**

- Support input with prefixkey + BLF and send numbers with it
- The SIP line of X3S was expanded to four
- Optimized the support for special characters '&' in phonebook
- Optimized the Hebrew and Arabic languages
- Optimized the LDAP related issues 5.
- Adjust the soud volumn of hotel phone H2S when calling or answering
- 7. **Built-in HTTPS certificates**
- 8. Optimized the LDAP to support the display of Menu and Contact at the same time



## 2 Bug Fixes

- Fixed the issue of the error of call logs in DND mode on phone
- Fixed the issue that adding more than 10 blacklist numbers in X3S/X4 while only having 10 after the restart.
- 3. Fixed the issue of failed X4 subscription
- 4. Fixed the issue of the failed X3S scramble
- 5. Fixed the issue of the incomplete content after the LDAP configuration
- Modify the problem that Multicast Paging doesn't show the content of Push Message
- 7. Fixed the issue that the tel format doesn't show the phone-context
- 8. Fixed the issue of the reminder function time prompt on LCD
- Fixed the issue that the line displayed on the phone page is inconsistent with the line displayed on the LCD
- 10. Modify the issue of opening the dial plate in non-predial mode can . Dial numbers more than seven digits will be covered
- 11. To modify the issue of the single pass of 3CX CallPark, you must first close the old one and then receive the new one
- 12. Modify the problem that the phone doesn't open RTP encryption and there is issue of RTP encryption field in package
- 13. Fixed the issue of the memory leak of WEB HTTPS
- 14. Fixed the problem that the outgoing call is failed in some cases
- 15. Fixed the problem that it is unable to use hot lines in screen saver status
- 16. Fixed the issue that X4 can not display the contacts in VOIP phone book
- 17. Fix the registration exception caused by STUN compatibility on 3CX server
- 18. Fixed an issue that CDP parsing is failed in some cases, resulting in an Fanvil Technology Co., Ltd



- exception on the phone
- 19. After the provision of LLDP VLAN is accepted by X3G, the Option66 Provision of mobile phone could not work
- 20. Fixed problems with abnormal bluetooth headsets in some cases
- 21. DssKey Line supports LED light display in SCA status
- 22. Fixed some server issues with SIP compatibility
- 23. Fix the problem that the phone is failed to call after the setting of hotline number on web page in hands-free mode.
- 24. When DHCP Offer carries more than 128 options, the phone may loop endlessly when receiving the offer
- 25. Fixed EHS to avoid using hands-free channels when calling
- 26. Fixed the problem under a situation where the phone could make a static deployment
- 27. Fixed the issue that the phone could not call with one click in MWI function
- 28. Fixed the issue of the long-time crash of X3G
- 29. Fixed the problem under some cases the phone was stuck in the communication interface and could not exit