



## Release Note

Software Version: 2.4.8.2.1

Models: H2U-V2

Date: 2022.8.19



# Content

---

<b>Content</b> .....	<b>2</b>
<b>1 Revise History</b> .....	<b>3</b>
<b>2 Release 2.4.8.2.1</b> .....	<b>4</b>
2.1 Optimization .....	4
<b>3 Release 2.4.8.1</b> .....	<b>5</b>
3.1 Differences between H2U and H2U-V2 .....	5
3.2 Optimization .....	5
3.3 Bug Fix .....	5

## 1 Revise History

---

No.	Version	Release Time
1	2.4.8.1	2022.5.5
2	2.4.8.2.1	2022.08.19

## 2 Release 2.4.8.2.1

---

<b>Models</b>	<b>Software Version</b>	<b>Comment</b>
H2U-V2	2.4.8.2.1	

### 2.1 Optimization

- 1.Optimize translation issues related to contacts

### 3 Release 2.4.8.1

---

Models	Software Version	Comment
H2U-V2	2.4.8.1	

#### 3.1 Differences between H2U and H2U-V2

	H2U Phone	H2U-V2 Phone
Model	H2U	H2U-V2
Vendor Identifier	Fanvil H2U	Fanvil H2U -V2
HTTP User Agent/ SIP User Agent	H2U	H2U-V2
Start-up speed	90S	20S
Codecs	G.711U,G.711A,G726,G.729AB ,iLBC,Opus,G.722	G.711U,G.711A,G726,G.729AB,iLBC ,Opus,G.722,G.723.1

#### 3.2 Optimization

1. Optimize the default hands-free volume value of 7
2. Modify the default configuration Check FailTimes to 1

#### 3.3 Bug Fix

1. Fix the problem of automatic deployment failure for special servers