



## Release Note

Software Version: 2.4.13.x

Models: X3SW/X3S (P) Lite/X3S (P) Pro/X3SGPro/X3SGLite/X3UPro

Date: 2023.11.17

## Content

---

<b>Content</b> .....	<b>2</b>
<b>1 Revise History</b> .....	<b>3</b>
<b>2 Release 2.4.13.x</b> .....	<b>4</b>
2.1 New Features .....	错误！未定义书签。
2.2 Optimization .....	4
<b>3 Release 2.4.12.5</b> .....	<b>5</b>
3.1 New Features .....	5
3.2 Optimization .....	5
3.3 Bug Fix .....	5
<b>4 Release 2.4.X</b> .....	<b>7</b>
4.1 Optimization .....	7
<b>5 Release 2.4.10.1</b> .....	<b>8</b>
5.1 New Features .....	8
5.2 Bug Fix .....	8

## 1 Revise History

---

No.	Version	Release Time
1	2.4.10.1	2022.1.7
2	2.4.X	2022.8.24
3	2.4.12.5	2023.2.13
4	2.4.13.x	2023.11.17

## 2 Release 2.4.13.x

---

<b>Models</b>	<b>Software Version</b>	<b>Comment</b>
X3SW/X3S(P)Lite/X3S(P)Pro/X3S GPro/X3SGLite/X3UPro	2.4.13.x	

### 2.1 Optimization

1. Enhanced the TR069 functionality.
2. Improved the call waiting feature.

### 3 Release 2.4.12.5

---

Models	Software Version	Comment
X3SW/X3S(P)Lite/X3S(P)Pro/X3S GPro/X3SGLite/X3UPro	2.4.12.5	

#### 3.1 New Features

3. Addition of Croatian
4. Add Japanese
5. Port SIP PBX Call Park Compatibility

#### 3.2 Optimization

1. Optimizing DNS Query Mode
2. Optimization of French-language translation documents
3. Optimization of automated deployment-related issues
4. Optimize the time to return the Dsskey Home interface from other Dsskey interfaces
5. Optimize the phone to receive calls with Reason field from Cancele as received calls in the call log
6. Extended LDAP Server Address Word Limit

#### 3.3 Bug Fix

1. Fix Phone Page Upgrade Dsskey Icon Help Message Error
2. Fix the problem that the LED light on the sub-screen of the phone does not change with the page number of the sub-screen

3. Fixing problems related to abnormalities in the use of Internet telephone books
4. Fix Unstable Phone Calls under WiFi
5. Fix the problem of sending STUN packets when STUN is turned off under special server
6. Fix the problem of delay in answering the call using the handle to set up the call

## 4 Release 2.4.X

---

<b>Models</b>	<b>Software Version</b>	<b>Comment</b>
X3SW/X3S (P) Lite/X3S (P) Pro/ X3SGPro/X3SGLite/X3UPro	2.4.X	

### 4.1 Optimization

- 1.Optimize translation issues related to contacts

## 5 Release 2.4.10.1

---

<b>Models</b>	<b>Software Version</b>	<b>Comment</b>
X3SW/X3S (P) Lite/X3S (P) Pro/ X3SGPro/X3SGLite/X3UPro	2.4.10.1	

### 5.1 New Features

1. IP Phone with color screen supports Caller ID Display
2. Add anti-degradation function to the phone
3. The phone supports setting startup logo image after it is upgraded on web page

### 5.2 Bug Fix

1. Fix the problem that the Wi-Fi MAC address displayed on the LCD of the phone does not match the actual Wi-Fi MAC address obtained by the phone



2. Fix the problem that the X3S Pro phone under the special server will prompt that the IP cannot be obtained after obtaining the address
  
3. Fix the problem that the screen displays a white screen after the phone upgrade version is completed under special circumstances