



Release Note

Software Version: 2.6.10.986

Models: V67

Date: 2024.3.15

Content

Content.....	2
1 Revise History.....	3
2 Release Version 2.6.10.986.....	4
2.1 New Features	4
2.2 Optimization.....	4
2.3 Bug Fix	4
3 Release Version 2.6.6.201	6
3.1 New Features	6
3.2 Optimization.....	6
3.3 Bug Fix	6
4 Release Version 2.6.6.187	8
4.1 Optimization.....	8

1 Revise History

No.	Version	Release Time
1	2.6.6.187	2022.12.23
2	2.6.6.201	2023.2.9
3	2.6.10.986	2024.3.15

2 Release Version 2.6.10.986

Models	Software Version	Comment
V67	2.6.10.986	

2.1 New Features

1. Iteratively update the brand new UI interface
2. Supports IPv6 and IPv4&IPv6 modes
3. Add the function of adding voice conference members through multiple selections
4. Add push XML function
5. Add DND large icon function

2.2 Optimization

1. Optimize the proxy interface to support the selection of proxy login status function
2. Optimize Block XML When Call configuration and adapt to push numeric buttons
3. Optimize key processing in the xmlbrowser section
4. Optimize the import function of Dsskey settings
5. Optimize compatibility issues with Ampitech access control cameras
6. Optimize software security issues

2.3 Bug Fix

1. Modify the issue of the phone not being able to answer calls when using the built-in app

Fanvil Technology Co., Ltd

Add: 10F, Block A, Dualshine Global Science Innovation Center, Honglang North 2nd Road, BaoAn District, Shenzhen, China
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com

2. Modify the issue of the phone not being able to refresh the session timer when establishing a call
3. Modify the hierarchy issue of Ldap phone book display type to List
4. Modify the color change issue of the softkey icon in the sliding pre dial interface
5. Modify the issue of not displaying XML phone book contacts on the webpage
6. Modify the issue of missing content in the Action URL issued by FDMCS

3 Release Version 2.6.6.201

Models	Software Version	Comment
V67	2.6.6.201	

3.1 New Features

1. Add Italian, Spanish and Kazakh

3.2 Optimization

1. Optimize the XML push function
2. Optimize the function of sending DTMF in full screen of video
3. Optimize French translation documents
4. Optimize auto-provision related issues

3.3 Bug Fix

1. Fix the issue where Dial Plan could not be deployed using a configuration file
2. Fix the issue that the Ring priority function did not take effect
3. Fix the issue where the remote end video could not be displayed during a video call
4. Fix the issue that contacts of VOIP phone book could not be found on the dial-up interface
5. Fix the issue that the webpage and LCD were not synchronized after enabling LDAP
6. Fix the issue that the phone cannot ping after setting the IPV6 static address in some cases
7. Fix the issue that MWI cannot call the mailbox number with one click when

Fanvil Technology Co., Ltd

Add: 10F, Block A, Dualshine Global Science Innovation Center, Honglang North 2nd Road, BaoAn District, Shenzhen, China
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com



there is no voice message

Fanvil Technology Co., Ltd

Add: 10F, Block A, Dualshine Global Science Innovation Center, Honglang North 2nd Road, BaoAn District, Shenzhen, China
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com

4 Release Version 2.6.6.187

Models	Software Version	Comment
V67	2.6.6.187	

4.1 Optimization

1. Optimize French translation documents